

	<b>LA1861M-TP-T1</b>	
	<b>Manufacturer Part Number:</b>	LA1861M-TP-T1
<b>Manufacturer/Brand:</b>	SANYO	
<b>Part of Description:</b>	SANYO SOP36	
<b>RoHs Status:</b>		
<b>Stock Condition:</b>	New original, 10500 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

### Specifications

Part Number	LA1861M-TP-T1
Manufacturer	SANYO
Description	SANYO SOP36
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	10500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

LA1861M-TP-T1 is New Original in Stock, Search LA1861M-TP-T1 Datasheets, PDF, Inventory at Y-IC.com Online, Order LA1861M-TP-T1 with warrantied and confidence. RFQ LA1861M-TP-T1 : Info@Y-IC.com

### You May Be Also Be interested

In:

 <b>LA1845NV-TLM-E</b> SANYO LA1845NV-TLM-E SANYO	 <b>LA1851N</b> SANYO LA1851N SANYO	 <b>LA1848</b> SANYO LA1848 SANYO	 <b>LA1867N</b> SANYO SANYO QFP
 <b>LA1863M-MPB</b> SANYO SANYO QFP	 <b>LA1845NV-MPB-E</b> SANYO LA1845NV-MPB-E SANYO	 <b>LA1862M-TE-R</b> SANYO SANYO SSOP-36	 <b>LA1862</b> SANYO SANYO SOP36

### Hot Parts

More

- |                      |                           |                         |                       |                       |
|----------------------|---------------------------|-------------------------|-----------------------|-----------------------|
| ⚙️ 04025A8R0JAT2A    | ➡️ 12101U100JAT2A         | ➡️ 150R140A             | D 1N5399GP-E3/73      | ➡️ 2MBI50U4A-060      |
| ⚡️ A3968ELBTR-T      | ⚙️ AD8055ARZ              | D ADSP-21363BBCZ-1AA    | ➡️ ATTINY461-15SZ     | ➡️ B0505S-1WR2        |
| ⚙️ BD6792FM-E2       | ⚡️ BWR-12/830-D48         | ⚙️ CGA8N4X7T2W474K230KA | ➡️ CHL8318-20.        | ➡️ CL-197HB1-D-T      |
| D DS1685E-5          | ⚙️ FAN53610AUC29X         | ⚡️ GQM1885C2A2R2CB01D   | ⚙️ GRM0335C2A8R1DA01J | ➡️ GRM31CR71H155KA88L |
| ➡️ IRFR15N20DTRLP    | ➡️ KSC2785-Y              | ⚙️ LT1521CST-3.3        | ⚡️ M50100TB200        | ➡️ M62006FP           |
| ➡️ MAX16933ATIR/V+T  | ➡️ MBR140SFT3G            | D MIC5207YM5-TR         | ⚙️ MMSZ4706-V         | ⚡️ NDS9948-NL         |
| ⚙️ PEC16-2225F-N0024 | D QSC-1110-0-284CSP-TR-0E | ➡️ RC0805FR-0756RL      | ➡️ SD200R25MSC        | ➡️ SI7956DP-T1-GE3    |
| ⚡️ SKBT40/08         | ⚙️ SMBJ7.0CA              | ➡️ SMP50-220-TR         | ➡️ SN74HCT374NSR      | ➡️ SPH3015H330MT      |
| ⚙️ SST4393-T1-GE3    | ⚡️ TC74LCX125FT           | ⚙️ TC74LVX4051FK        | D TC74VHC9541FT       | ➡️ TLV320ADC3101IRGER |
| ➡️ TP13054BN         | ⚙️ UBA2212CT/N1           | ⚡️ UC3844BVDR2          | ⚙️ WG6009F            | ➡️ XC6209F15AMRN      |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited