



 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">SPX1583T5-L-2-5/TR</h2>
	<p>Manufacturer Part Number: SPX1583T5-L-2-5/TR</p> <p>Manufacturer/Brand: SIPEX</p> <p>Part of Description: SIPEX TO263</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 3300 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications	
Part Number	SPX1583T5-L-2-5/TR
Manufacturer	SIPEX
Description	SIPEX TO263
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	3300 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

SPX1583T5-L-2-5/TR is New Original in Stock, Search SPX1583T5-L-2-5/TR Datasheets, PDF, Inventory at Y-IC.com Online, Order SPX1583T5-L-2-5/TR with warrantied and confidence.
RFQ SPX1583T5-L-2-5/TR : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>SPX1584AT-5.0 SIPEX SPX1584AT-5.0 SIPEX</p>	 <p>SPX1583T5-L Exar Corporation IC REG LDO ADJ 1.5A TO263-5</p>	 <p>SPX1582U5 SIPEX SPX1582U5 SIPEX</p>	 <p>SPX1584U SIPEX SPX1584U SIPEX</p>
 <p>SPX1583T5 SIPEX SPX1583T5 SIPEX</p>	 <p>SPX1584AT SIPEX SPX1584AT SIPEX</p>	 <p>SPX1583T5-3.3 SIPEX SIPEX SOT 5PI</p>	 <p>SPX1583T5-2.5 SIPEX SPX1583T5-2.5 SIPEX</p>

Hot Parts

More

- | | | | | |
|--------------------|---------------------|-----------------------|-------------------------|--------------------|
| ⚙️ 08052C561KAT9A | ➡️ 12061A121MAT2A | ➡️ 1808CC153KATME | D 28F0121-0SR | ➡️ A52HA0.4A-B |
| ⚡️ B39212B8510P810 | ⚙️ BA10358F-E2 | D BA6195FP-Y | ➡️ BLM21BD222TN1D | ➡️ BSO104N3S |
| ⚙️ BU24591-81 | ⚡️ C0603X5R1H471M | ⚙️ CAT5118SBI-50-T | ➡️ CGJ4J2C0G1H223J125AA | ➡️ CPC7593ZCTR |
| D F951C335MPAAQ2 | ⚙️ FESF8JT-E3/45 | ⚡️ GRM022R61A102KE19L | ⚙️ IRF6617TR1 | ➡️ ISL9N306AD3ST |
| ➡️ IXTN36N50 | ➡️ KE524575 | ⚙️ LFD18820MDP9C209 | ⚡️ LM26CIM5-SHA | ➡️ LPC1756FBD80 |
| ➡️ LT1424IS8-5#PBF | ➡️ LT1716HS5#TRMPBF | D LTC6801HG#PBF | ⚙️ M29W640FB70ZA6 | ⚡️ MDA600-16N1 |
| ⚙️ MIC2536-1YM | D NCV33064D-5R2G | ➡️ NRH3012T220MNM | ➡️ P6KE33A-E3/73 | ➡️ RC0603FR-072K7L |
| ⚡️ RGLN2012080A4T | ⚙️ RJK1560DPP-M0 | ➡️ RT9161-50GX | ➡️ RT9705APC | ➡️ SMBT1335LT1 |
| ⚙️ SML-311DTT86J | ⚡️ TJA1028T/5V0/10 | ⚙️ TLV431IDBZR | D TMPA2010DMCR | ➡️ TPA3009D2PHPR |
| ➡️ TPS62020DGQR | ⚙️ TPSMA33A-E3/61T | ⚡️ V300A12C500BL | ⚙️ VI-2N0-EU | ➡️ VI-JTZ-IY |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited