

	<h2 style="color: #E67E22;">MAX6864UK16D1L+T</h2>	
	Manufacturer Part Number:	MAX6864UK16D1L+T
	Manufacturer/Brand:	Maxim Integrated
	Part of Description:	IC MPU SUPERVISOR SOT23-5
Datasheets:	1.MAX6864UK16D1L+T.pdf 2.MAX6864UK16D1L+T.pdf	
RoHs Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications

Part Number	MAX6864UK16D1L+T
Manufacturer	Maxim Integrated
Description	IC MPU SUPERVISOR SOT23-5
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	10 ms Minimum
Voltage - Threshold	1.575V
Packaging	Tape & Reel (TR)

MAX6864UK16D1L+T is New Original in Stock, Search MAX6864UK16D1L+T Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX6864UK16D1L+T Maxim Integrated with warrantied and confidence. RFQ MAX6864UK16D1L+T : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MAX6863UK30+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6864UK16D3L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6864UK16D1S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6864UK17D3S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>
 <p>MAX6864UK16D3L+ MAXIM MAX6864UK16D3L+ MAXIM</p>	 <p>MAX6863UK28+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6864UK16D3S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6864UK16D1L+ Maxim Integrated IC SUPERVISOR</p>

Hot Parts

More

- | | | | | |
|----------------------|---------------------|---------------------|--------------------|--------------------|
| 06031C472JAZ2A | 1MBI600LP-060 | AR9132-BC1E | D AT24C32CN-SH-B | BK1608HM121-T |
| C0603C0G1E090C030BG | CL21B102JBANNC | D CMM6001G-SC | DF20AA140 | DMP3098LSS-13-HN |
| DS1721U+ | ELM9818AB-S/N | GRB24250D-2W-B | GRM033R61C333ME84J | GRM1555C1H4R3WZ01D |
| D GRM2165C1H272JA01D | GT300AL-22 | H-A200S2 | IPS105N03L | IRFR214BTF |
| K4M51323PG-HG75 | KAA-3528ESGC | LFE2M50E-6FN900C-5I | LM4836LQX | LNK6769K |
| LP2966IMM-3030 | LSP4054CAD | D MAX4435ESA | MIC4225YMTR | NCP18WB473F10RB |
| OPA4704UA | D PACDN042YB3 | PS21245-E | PT2332-X | RT9181-18CB |
| RX-8801SAUB | S12ME1IY | S29JL032H90TAIT10 | SC1176TS | SI4911DY-T1-E3 |
| STB13NK60Z-1 | STC11F02-35I-SOP20G | STM32F103RCY6TR | D T44-15SSZ | TLE4945-2L |
| TPS2216DB | TS8121CXLF | TZ530N30KOF | UMK105CK010DV-F | UQCL2A1R0BAT2A\500 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited