









 <p>A Renesas Company</p>	<p><b>ISL33001IUZ</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">ISL33001IUZ</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <p><b>Part of Description:</b> IC ACCELERATOR I2C HOTSWAP 8MSOP</p> <p><b>Datasheets:</b> <a href="#">ISL33001IUZ.pdf</a></p> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	<a href="#">ISL33001IUZ</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC ACCELERATOR I2C HOTSWAP 8MSOP
Category	<a href="#">Integrated Circuits (ICs) &gt; Interface - Signal Buffers,</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Current - Supply	4mA
Operating Temperature	-40°C ~ 85°C
Type	Buffer, Accelerator
Number of Channels	2
Applications	I <sup>2</sup> C - Hotswap
Package / Case	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Supplier Device Package	8-MSOP
Voltage - Supply	2.3 V ~ 5.5 V
Output	2-Wire Bus
Input	2-Wire Bus
Delay Time	-
Data Rate (Max)	-
Signal Conditioning	-
Capacitance - Input	10pF
Packaging	Tube

ISL33001IUZ is New Original in Stock, Search ISL33001IUZ Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL33001IUZ Intersil with warrantied and confidence. RFQ ISL33001IUZ : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<p>In:</p>  <p><b>ISL33001IBZ-T</b> Intersil IC ACCELERATOR I2C HOTSWAP 8SOIC</p>	 <p><b>ISL33001IRTZ-T</b> Intersil IC ACCELERATOR I2C HOTSWAP 8TDFN</p>	 <p><b>ISL33001IRT2Z</b> Intersil IC ACCELERATOR I2C HOTSWAP 8TDFN</p>	 <p><b>ISL33002IRT2Z</b> Intersil IC ACCELERATOR I2C HOTSWAP 8TDFN</p>
 <p><b>ISL33001IUZ-T</b> Intersil IC ACCELERATOR I2C HOTSWAP 8MSOP</p>	 <p><b>ISL33002IRT2Z-T</b> Intersil IC ACCELERATOR I2C HOTSWAP 8TDFN</p>	 <p><b>ISL33001IRTZ</b> Intersil IC ACCELERATOR I2C HOTSWAP 8TDFN</p>	 <p><b>ISL33001IRT2Z-T</b> Intersil IC ACCELERATOR I2C HOTSWAP 8TDFN</p>

### Hot Parts

[More](#)

<a href="#">0402ZG823ZAT2A</a>	<a href="#">08051C223KAT4A</a>	<a href="#">1812AA821KAT1A\SB</a>	<a href="#">1812AC102ZAT1A</a>	<a href="#">1812CC473MAT1A\SB</a>
<a href="#">A6300AE5R-30A</a>	<a href="#">AD8033ARZ</a>	<a href="#">AD8692ARZ</a>	<a href="#">ADM3053BRWZ</a>	<a href="#">AT45DB081B-CNU</a>
<a href="#">B39389-K3953-N201</a>	<a href="#">BTW68-800RG</a>	<a href="#">BY228-TAP</a>	<a href="#">BYC10X-600</a>	<a href="#">C4520C0G3F180K110KA</a>
<a href="#">CGA2B2C0G1H220J050BD</a>	<a href="#">CL10C221JB8NFNC</a>	<a href="#">D2200N20</a>	<a href="#">D67S1000U</a>	<a href="#">DG201HSDY</a>
<a href="#">DS2103SY21</a>	<a href="#">FD650B-S</a>	<a href="#">FFAF05U120DNTU</a>	<a href="#">GRM1555C1H3R4BA01D</a>	<a href="#">GRM188R71H392KA01D</a>
<a href="#">ICS650R-11I</a>	<a href="#">KTC3199-GR-AT/P</a>	<a href="#">L4931CD45-TR</a>	<a href="#">L4931CDT35TR</a>	<a href="#">LD061C104KAB4A</a>
<a href="#">LM2937ES-9.0</a>	<a href="#">MAX6120EUR</a>	<a href="#">MAX6691MUB+T</a>	<a href="#">MC7447BHX1420RFR</a>	<a href="#">NCP1835BMNR2G</a>
<a href="#">P086PH10FJ0</a>	<a href="#">P540C0101</a>	<a href="#">PIC18F2580-I/ML</a>	<a href="#">PIP3207-DC</a>	<a href="#">SC1545CS</a>
<a href="#">SC508796CFU</a>	<a href="#">SF48S5-10W/F</a>	<a href="#">SI-3018KM2</a>	<a href="#">SI8050SD</a>	<a href="#">T494A225K020AT</a>
<a href="#">TC358891WBG</a>	<a href="#">TPS65530ARSLR</a>	<a href="#">VI-260-29</a>	<a href="#">XC6222C351MR-G</a>	<a href="#">ZUS151212</a>

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited