










 <p>A Renesas Company</p>	<h2>ISL3159EIBZ</h2>
	<p><b>Manufacturer Part Number:</b> <a href="#">ISL3159EIBZ</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <p><b>Part of Description:</b> IC TXRX 5V RS485 RS422 8SOIC</p> <p><b>Datasheets:</b>  <a href="#">ISL3159EIBZ.pdf</a></p> <p><b>RoHs Status:</b>  Lead free / RoHS Compliant</p> <p><b>Stock Condition:</b> New original, 17250 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	<a href="#">ISL3159EIBZ</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC TXRX 5V RS485 RS422 8SOIC
Category	<a href="#">Integrated Circuits (ICs) &gt; Interface - Drivers,</a>
Part Status	17250 pcs Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Voltage - Supply	4.5 V ~ 5.5 V
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Half
Receiver Hysteresis	28mV
Data Rate	40Mbps
Packaging	Tube

ISL3159EIBZ is New Original in Stock, Search ISL3159EIBZ Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL3159EIBZ Intersil with warrantied and confidence. RFQ  
ISL3159EIBZ : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested In:

 <p><b>ISL3159EFRZ-T</b> Intersil IC TXRX 5V RS485 RS422 10DFN</p>	 <p><b>ISL3159EFUZ</b> Intersil IC TXRX 5V RS485 RS422 8MSOP</p>	 <p><b>ISL3159EFRZ-T7A</b> Intersil IC TXRX 5V RS485 RS422 10DFN</p>	 <p><b>ISL3159EFUZ-T7A</b> Intersil IC TXRX 5V RS485 RS422 8SOIC</p>
 <p><b>ISL3159EIRZ</b> Intersil IC TXRX 5V RS485 RS422 10DFN</p>	 <p><b>ISL3159EIBZ-T7A</b> Intersil IC TXRX 5V RS485 RS422 8SOIC</p>	 <p><b>ISL3159EIBZ-T</b> Intersil IC TXRX 5V RS485 RS422 8SOIC</p>	 <p><b>ISL3159EIRZ-T</b> Intersil IC TXRX 5V RS485 RS422 10DFN</p>

### Hot Parts

[More](#)

<a href="#">ISL3084IZ</a>	<a href="#">ISL3092IR-TK</a>	<a href="#">ISL3092IRZ</a>	<a href="#">ISL3092IRZ-TK</a>	<a href="#">ISL3140MZ</a>
<a href="#">ISL31472EIBZ</a>	<a href="#">ISL31475EIBZ</a>	<a href="#">ISL31485EIBZ</a>	<a href="#">ISL31486EIBZ</a>	<a href="#">ISL31492EIBZ</a>
<a href="#">ISL31492EIUZ-T</a>	<a href="#">ISL31493EIUZ</a>	<a href="#">ISL31495EIBZ</a>	<a href="#">ISL31498EIBZ</a>	<a href="#">ISL3150EIUZ-T</a>
<a href="#">ISL3152EIBZ</a>	<a href="#">ISL3152EIBZ-T</a>	<a href="#">ISL3153EIBZ</a>	<a href="#">ISL3153EIUZ-T</a>	<a href="#">ISL3155EIBZ</a>
<a href="#">ISL3156EIBZ</a>	<a href="#">ISL3156EIUZ</a>	<a href="#">ISL3158EIBZ</a>	<a href="#">ISL3159EFBZ</a>	<a href="#">ISL3159EFUZ-T</a>
<a href="#">ISL3159EIBZ-T</a>	<a href="#">ISL3159EIRZ</a>	<a href="#">ISL3170EIUZ</a>	<a href="#">ISL3171EIBZ</a>	<a href="#">ISL3172EIBZ</a>
<a href="#">ISL3172EIBZ-T</a>	<a href="#">ISL3173EIBZ</a>	<a href="#">ISL3175EIBZ</a>	<a href="#">ISL3175EIBZ-T</a>	<a href="#">ISL3176EIBZ</a>
<a href="#">ISL3176EIUZ</a>	<a href="#">ISL3177EIBZ</a>	<a href="#">ISL3178EIBZ</a>	<a href="#">ISL3178EIBZ-T</a>	<a href="#">ISL3178EIUZ</a>
<a href="#">ISL3178EIUZ-T</a>	<a href="#">ISL3179EFUZ-T</a>	<a href="#">ISL3179EIBZ-T</a>	<a href="#">ISL3183IR</a>	<a href="#">ISL3183IR96</a>
<a href="#">ISL32172EIBZ</a>	<a href="#">ISL32175EIBZ</a>	<a href="#">ISL3221EIVZ</a>	<a href="#">ISL3222ECP</a>	<a href="#">ISL32272EFVZ</a>

Contact us:[Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited