








	<p>X9015UM8I-2.7T2</p>
	<p>Manufacturer Part Number: X9015UM8I-2.7T2</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC XDCP SGL 32-TAP 50K 8-MSOP</p> <p>Datasheets: X9015UM8I-2.7T2.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	X9015UM8I-2.7T2
Manufacturer	Intersil
Description	IC XDCP SGL 32-TAP 50K 8-MSOP
Category	Integrated Circuits (ICs) > Data Acquisition - Digital
Part Status	Require For Quote & Check Stock
Series	XDCP™
Operating Temperature	-40°C ~ 85°C
Features	-
Interface	Up/Down (U/D, INC, CS)
Configuration	Potentiometer
Tolerance	±20%
Package / Case	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Supplier Device Package	8-MSOP
Number of Circuits	1
Voltage - Supply	2.7 V ~ 5.5 V
Memory Type	Volatile
Resistance (Ohms)	50k
Taper	Linear
Number of Taps	32
Temperature Coefficient (Typ)	±300 ppm/°C
Resistance - Wiper (Ohms) (Typ)	400
Packaging	Tape & Reel (TR)

X9015UM8I-2.7T2 is New Original in Stock, Search X9015UM8I-2.7T2 Datasheets, PDF, Inventory at Y-IC.com Online, Order X9015UM8I-2.7T2 Intersil with warrantied and confidence. RFQ X9015UM8I-2.7T2 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>X9015UM8IZT1 Intersil IC XDCP SGL 32-TAP 50K 8-MSOP</p>	 <p>X9015UM8IZ Intersil IC XDCP SGL 32-TAP 50K 8-MSOP</p>	 <p>X9015UM8IT1 Intersil IC XDCP SGL 32-TAP 50K 8-MSOP</p>	 <p>X9015UM8I-2.7 Intersil IC XDCP SGL 32-TAP 50K 8-MSOP</p>
 <p>X9015UM8-2.7 Intersil IC XDCP SGL 32-TAP 50K 8-MSOP</p>	 <p>X9015UM8IZ-2.7T1 Intersil IC XDCP SGL 32-TAP 50K 8-MSOP</p>	 <p>X9015UM8I-2.7T1 Intersil IC XDCP SGL 32-TAP 50K 8-MSOP</p>	 <p>X9015UM8-2.7T1 Intersil IC XDCP SGL 32-TAP 50K 8-MSOP</p>

Hot Parts

[More](#)

⊛ 08051U6R8BAT2A	↔ 12061A751FAT2A	⇒ 1600FD21	D 18122A562KAT2A	⇒ ACT512US
⊣ AP1501A-33T5L	⊛ BLM41PF800SN1L	D BZT52C2V4T1G	⇒ C1608CH1H103K080AA	⇒ C8051T611-GMR
⊛ CC0402DRNPO9BN6R0	⊣ CGA5L3X7R1H225K160AB	⊛ CL31B103KGFNNNF	↔ CY62256LL-70SNXIT	⇒ D150N28B
D D2601N90T	⊛ GQM1555C2D3R4BB01D	⊣ GRM2196P2A160JZ01D	⊛ IR3629AMTRPBF.	⇒ ITS4200S-ME-P
⇒ KSH200TF	↔ LM3171LDT	⊛ LTC1504ACS8-3.3	⊣ LXES15AAA1-133	⇒ MA3DF46000RP
↔ MBR20100CTP	⇒ MC68HC11K1FU4	D MC7808BD2TR4	⊛ MCP2050-500/SL	⊣ MIC2951-03YM
⊛ MP62171ES-LF-Z	D NCP1403SNT1G	⇒ NCP3235MNTXG	↔ NCP4688DSN28T1G	⇒ NCP715SQ33T2G
⊣ PESD3V3L4UF	⊛ PS2565-1	↔ S-8353A36UA-IQVT2G	⇒ SG50C-40	⇒ SKKL91/08D
⊛ SST12LP19E-QX8E	⊣ SSTPAD500	⊛ SW18DXC16C	D TCM1210U-120-2P-T000	⇒ TK11213BMCL
↔ TLV5637CDRG4	⊛ TPS5120DBTR	⊣ TT215N08KOF	⊛ VI-B03-EX	⇒ Z240D10

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited