

 <p>A Renesas Company</p>	<p>HIN232IP</p>
	<p>Manufacturer Part Number: HIN232IP</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC 2DRVR/2RCVR RS232 5V 16-DIP</p> <p>Datasheets:  HIN232IP.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	HIN232IP
Manufacturer	Intersil
Description	IC 2DRVR/2RCVR RS232 5V 16-DIP
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Through Hole
Type	Transceiver
Package / Case	16-DIP (0.300", 7.62mm)
Supplier Device Package	16-PDIP
Voltage - Supply	4.5 V ~ 5.5 V
Protocol	RS232
Number of Drivers/Receivers	2/2
Duplex	Full
Receiver Hysteresis	500mV
Data Rate	120Kbps
Packaging	Tube

HIN232IP is New Original in Stock, Search HIN232IP Datasheets, PDF, Inventory at Y-IC.com Online, Order HIN232IP Intersil with warrantied and confidence. RFQ HIN232IP : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>HIN235CP HAR HIN235CP HAR</p>	 <p>HIN232IBE INTERSIL HIN232IBE INTERSIL</p>	 <p>HIN232IBNZ-T Intersi Intersi SOP-16</p>	 <p>HIN236CB Intersil IC 4DRVR/3RCVR RS232 5V 24-SOIC</p>
 <p>HIN232IBZ Intersil IC 2DRVR/2RCVR RS232 5V 16-SOIC</p>	 <p>HIN232IBZ-T Intersil IC 2DRVR/2RCVR RS232 5V 16-SOIC</p>	 <p>HIN232IBNZ INT HIN232IBNZ INT</p>	 <p>HIN232IPZ Intersil IC 2DRVR/2RCVR RS232 5V 16-DIP</p>

Hot Parts

[More](#)

- | | | | | |
|-------------------------------------|---------------------------------------|---|------------------------------------|--------------------------------|
| 5STP03A1200 | AOZ1977AI-01 | AT89S52-24JI | BCM856SE6327 | C1005Y5V1E224Z |
| C2012X5R1V106K125AC | CX20752-21Z | CY74FCT163952CPVC | DSI17-04A | DTA143XUA |
| FSV10120V | GJM0225C1E5R4DB01L | HLE-104-02-G-DV-BE-P-TR | IA1205S-W5 | IPB15N03L |
| IRFU430B | IRU1030-33CDTR | IXTQ200N06P | KSH44H11TM-NL | L7812CV/AT |
| LB2518T102M | LM2704MFX-ADJ | LP8552TLX-E00 | M93C86-MN6TP | MAX674EPA |
| MAX8857AETL+T | MB95007LPU-G-102-EFE1 | MCD501-14IO2 | MCP4024T-502E/OT | MD2202-D16-X |
| MEE75-12DA | MXHV9910BATR | PAM8902AZER | PI5C3306LEX | RB551V-30TE |
| RF3161SR | RK73H1JTDD8201F | RN5VD42AA-TL-FA | S29GL256P90TFCR20D | SBR6150CTL |
| SEMIX252GB176HDS | SMAJ22-6606 | SMCJ5.0A | TAJD476K010RNJ | TC74AC138P |
| TLC7733FMKB | TLV2352IDR | TPSMB24A | TS1117CPRO | TSB15LV01PFC |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited