









	<h2 style="color: #E67E22;">ZL40225LDG1</h2>	
	Manufacturer Part Number:	ZL40225LDG1
	Manufacturer/Brand:	Microsemi
	Part of Description:	IC CLK BUFF MUX 2:8 750MHZ 32QFN
	Datasheets:	1.ZL40225LDG1.pdf 2.ZL40225LDG1.pdf 3.ZL40225LDG1.pdf
RoHS Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications

Part Number	ZL40225LDG1
Manufacturer	Microsemi
Description	IC CLK BUFF MUX 2:8 750MHZ 32QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution), Multiplexer
Frequency - Max	750MHz
Package / Case	32-VFQFN Exposed Pad
Supplier Device Package	32-QFN (5x5)
Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.465 V
Output	LVPECL
Input	CML, HCSSL, LVCMOS, LVDS, LVPECL
Ratio - Input:Output	2:8
Differential - Input:Output	Yes/Yes
Packaging	Tray

ZL40225LDG1 is New Original in Stock, Search ZL40225LDG1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40225LDG1 Microsemi with warrantied and confidence. RFQ
 ZL40225LDG1 : Info@Y-IC.com

You May Be Also Be interested

In:  ZL40223LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN	 ZL40224LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN	 ZL40226LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN	 ZL40223LDG1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN
 ZL40226LDG1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN	 ZL40225LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN	 ZL40230LDF1 Microsemi LOW SKEW, LOW ADDITIVE JITTER 3	 ZL40227LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN

Hot Parts

[More](#)

- | | | | | |
|-------------------------|--------------------------|-----------------------|-----------------------|------------------|
| ⚙️ 08055A821FAT4A | ➡️ 1812GC272MAT9A | ➡️ 302R29W102KV4E | D 5STP06D2600 | ➡️ ACT365SH-T |
| ⚡️ ADP3338AKC-5.0-RL7 | ⚙️ B39132-B1641-U510-W03 | D BB504CDS-TL-EQ | ➡️ BT168W-500R | ➡️ BTS3046SDL |
| ⚙️ CGA4J3X7R1E155M125AB | ⚡️ CL31B471KGFNFNE | ⚙️ CS1616-FZZR | ➡️ D34N800C | ➡️ F971C475MBA |
| D FDMS9411 | ⚙️ GRM0335C1E101FA01J | ⚡️ GRM31A7U2J102JW31D | ⚙️ HGTG7N60A4 | ➡️ INA2137UA/2K5 |
| ➡️ ISL60002BIH311Z-TK | ➡️ LA8522JG | ⚙️ LT1074CT#PBF | ⚡️ LTC1861IMS#PBF | ➡️ MAX495EPA |
| ➡️ MAX6801UR29D2+T | ➡️ MAX705CUA+ | D MB8873HM-G | ⚙️ MCP6002-EMS | ⚡️ MDS1660URH |
| ⚙️ MLK1005S6N8DT000 | D N0882NC450 | ➡️ NLC322522T-6R8M | ➡️ NUS5531MTR2G | ➡️ OPA4137UA |
| ⚡️ PD69108ILQ-TR | ⚙️ PR33MF51NSZF | ➡️ RA203425XX00 | ➡️ RS2J-E3/52T | ➡️ SCAN921025SLC |
| ⚙️ SKKD700/22 | ⚡️ SMBJ16CA | ⚙️ SMBJ48A-E3/61 | D SSTA13T116 | ➡️ STC12C5604 |
| ➡️ SW-602B-P | ⚙️ SW2DG-H8D-4K | ⚡️ TL074ACN | ⚙️ UPD9972F1-AA2-E2-A | ➡️ W2052NC360 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited