	<p><b>STRF6553</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">STRF6553</a></p> <p><b>Manufacturer/Brand:</b> SK</p> <p><b>Part of Description:</b> SK TO3P-5</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 2000 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









**Specifications**

Part Number	STRF6553
Manufacturer	SK
Description	SK TO3P-5
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	2000 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

STRF6553 is New Original in Stock, Search STRF6553 Datasheets, PDF, Inventory at Y-IC.com Online, Order STRF6553 with warrantied and confidence. RFQ STRF6553 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p><b>STRF6552</b> SK SK TO3P-5</p>	 <p><b>STRF6626</b> SANKEN SANKEN TO-3P</p>	 <p><b>STRF6555</b> SANKEN SANKEN TO-3P</p>	 <p><b>STRF6624</b> SANKEN SANKEN TO-3P</p>
 <p><b>STRF6616</b> SK SK SIP-5P</p>	 <p><b>STRF6524</b> SK SK TO3P-5</p>	 <p><b>STRF6516</b> SANKEN SANKEN ZIP-5</p>	 <p><b>STRF6523H</b> SK SK SIP-5P</p>

Hot Parts

[More](#)

- |                         |                       |                       |                      |                      |
|-------------------------|-----------------------|-----------------------|----------------------|----------------------|
| ⊛ 06036C222KAT4A        | ↔ 12065C683JAT2A      | ⇒ 121926-03300880     | D AD5203ARUZ100-REEL | ⇒ ATM90E32AS-AU      |
| ↳ B39262-B8325-P810-S05 | ⊛ BA25BC0FP-RE2       | D C0603COG1H150JT00NN | ⇒ C1608COG1H180J/10  | ⇒ C1608CH2E181K080AA |
| ⊛ C3216CH1H683K160AA    | ↳ CX3225SB3200D0FLFZZ | ⊛ DAC7731EB           | ↔ ECLAMP2388P.TCT    | ⇒ FQA13N80           |
| D GRM0335C2A6R8CA01J    | ⊛ HA17339F-TL         | ↳ HAT2028RJ-EL        | ⊛ HSMP-4810          | ⇒ IRF7352D2TRPBF.    |
| ⇒ K7M163625A-QC65       | ↔ LM3424QMHX/NOPB     | ⊛ LM79L12ACM          | ↳ LTC2904ITS8#TRPBF  | ⇒ MCD225-12IO1B      |
| ↔ MM3099EYREH           | ⇒ MSM6323BMS-KR4      | D NDS8961-NL          | ⊛ NFC10-12S12        | ↳ NLFV25T-3R3M-PF    |
| ⊛ PQ015EZ02ZP           | D PTN3310D            | ⇒ RR263M-400          | ↔ SA15C-E3/54        | ⇒ SC211-2-TE12RA     |
| ↳ SC427242CFAR2         | ⊛ SFHG56JA002         | ↔ SMD100F/33-2        | ⇒ SN74ALS27ANSR      | ⇒ STPS20L60CT        |
| ⊛ TH72001.2             | ↳ TLC272ACDR          | ⊛ UCC28630D           | D US168ESE           | ⇒ V24B15C200AL2      |
| ↔ VI-25Z-EX             | ⊛ VI-J0J-CY           | ↳ WG82583V            | ⊛ X4043M8Z           | ⇒ XRF4324            |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited