








	<h2 style="color: red;">LB1867M-TLM-E</h2>	
	Manufacturer Part Number:	LB1867M-TLM-E
	Manufacturer/Brand:	AMI Semiconductor / ON Semiconductor
	Part of Description:	IC MOTOR DRIVER ON/OFF 14MFP
Datasheets:	 LB1867M-TLM-E.pdf	
RoHs Status:	 Lead free / RoHS Compliant	
Stock Condition:	New original, 1127 pcs Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

Specifications

Part Number	LB1867M-TLM-E
Manufacturer	AMI Semiconductor / ON Semiconductor
Description	IC MOTOR DRIVER ON/OFF 14MFP
Category	Integrated Circuits (ICs) > PMIC - Full, Half-Bridge
Part Status	1127 pcs Stock
Series	-
Technology	Bipolar
Operating Temperature	-30°C ~ 80°C (TA)
Mounting Type	Surface Mount
Features	-
Interface	Logic
Applications	DC Motors, General Purpose
Package / Case	14-LSOP (0.173", 4.40mm Width)
Supplier Device Package	14-MFPS
Voltage - Supply	6.4 V ~ 7 V
Current - Output / Channel	1A
Current - Peak Output	-
Output Configuration	Half Bridge (2)
Fault Protection	Over Temperature
Load Type	Inductive
Rds On (Typ)	-
Voltage - Load	12V, 24V
Packaging	Tape & Reel (TR)

LB1867M-TLM-E is New Original in Stock, Search LB1867M-TLM-E Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1867M-TLM-E AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ LB1867M-TLM-E : Info@Y-IC.com

You May Be Also Be interested In:

 <p>LB1863M-TLM-H AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER ON/OFF 14MFP</p>	 <p>LB1867M-MPB-H AMI Semiconductor / ON Semiconductor IC BRIDGE DRIVER ON/OFF MFP14S</p>	 <p>LB1867M-MPB-E AMI Semiconductor / ON Semiconductor IC BRIDGE DRIVER ON/OFF MFP14S</p>	 <p>LB1867M SANYO LB1867M SANYO</p>
 <p>LB1867 SANYO LB1867 SANYO</p>	 <p>LB1868 SANYO LB1868 SANYO</p>	 <p>LB1867M-TLM-H AMI Semiconductor / ON Semiconductor IC BRIDGE DRIVER ON/OFF MFP14S</p>	 <p>LB1868M-NMB-TLM3-E SANYO LB1868M-NMB-TLM3-E SANYO</p>

Hot Parts

[More](#)

- | | | | | |
|----------------------|-----------------------|-----------------|-------------------|--------------------|
| ⊗ LB1839M-TE-R | ↔ LB1839ML-TP-T1 | ⇒ LB1841V-MPB-E | D LB1843V-S-TRM-E | ⇒ LB1843V-TLM-E |
| ⊣ LB1845L-S-E | ⊗ LB1848M-MPB-H | D LB1848M-TE-R | ⇒ LB1848M-TRM-E | ⇒ LB1860M-ND-TLM-E |
| ⊗ LB1860M-TE-L | ⊣ LB1860M-TLM-E | ⊗ LB1860M-TLM-H | ↔ LB1861M-TE-L | ⇒ LB1861M-TLM-E |
| D LB1861M-TLM-H | ⊗ LB1862M-NMB-TLM3-E | ⊣ LB1862M-TE-L | ⊗ LB1862M-TLM-E | ⇒ LB1862M-TLM-H |
| ⇒ LB1862MC-AH | ↔ LB1863M-DELTA-TLM-H | ⊗ LB1863M-TE-L | ⊣ LB1863M-TLM-H | ⇒ LB1867M-MPB-H |
| ↔ LB1868M-NMB-TLM3-E | ⇒ LB1868M-TE-L | D LB1868M-TLM-E | ⊗ LB1868M-TLM-H | ⊣ LB1869M-TLM-E |
| ⊗ LB1870M-TE-L | D LB1877V-MPB-E | ⇒ LB1877V-TLM | ↔ LB1879M-TE-L | ⇒ LB1906CL-TLM |
| ⊣ LB1906CL-TLM-E | ⊗ LB1921-E | ↔ LB1923M-TE-L | ⇒ LB1923M-TLM-E | ⇒ LB1924A-E |
| ⊗ LB1930M-TLM | ⊣ LB1930M-TLM-E | ⊗ LB1930MC-AH | D LB1933M-MPB-E | ⇒ LB1934T-MPB-E |
| ↔ LB1935CL-TLM-E | ⊗ LB1935FA-AH | ⊣ LB1935T-TLM-E | ⊗ LB1936V-MPB-E | ⇒ LB1936V-TLM |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited