





| | |
|---|---|
|  | <h2 style="color: #E67E22;">CAT863TTBI-GT3</h2> |
| | <p>Manufacturer Part Number: CAT863TTBI-GT3</p> <p>Manufacturer/Brand: AMI Semiconductor / ON Semiconductor</p> <p>Part of Description: IC SUPERVISOR MPU OD 3.08V SOT23</p> <p>Datasheets:  CAT863TTBI-GT3.pdf</p> <p>RoHs Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
|  | |
| <p>Image may be representation. See specs for product details.</p> | |








Specifications

| | |
|------------------------------|--|
| Part Number | CAT863TTBI-GT3 |
| Manufacturer | AMI Semiconductor / ON Semiconductor |
| Description | IC SUPERVISOR MPU OD 3.08V SOT23 |
| Category | Integrated Circuits (ICs) > PMIC - Supervisors |
| Part Status | Require For Quote & Check Stock |
| Series | - |
| Operating Temperature | -40°C ~ 85°C (TA) |
| Mounting Type | Surface Mount |
| Type | Simple Reset/Power-On Reset |
| Package / Case | TO-236-3, SC-59, SOT-23-3 |
| Supplier Device Package | SOT-23-3 |
| Output | Open Drain or Open Collector |
| Reset | Active Low |
| Number of Voltages Monitored | 1 |
| Reset Timeout | 140 ms Minimum |
| Voltage - Threshold | 3.08V |
| Packaging | Tape & Reel (TR) |

CAT863TTBI-GT3 is New Original in Stock, Search CAT863TTBI-GT3 Datasheets, PDF, Inventory at Y-IC.com Online, Order CAT863TTBI-GT3 AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ CAT863TTBI-GT3 : Info@Y-IC.com

You May Be Also Be interested

In:

| | | | |
|--|--|---|--|
|  <p>CAT872-15ULGT3 ON CAT872-15ULGT3 ON</p> |  <p>CAT872-30ULGT3 AMI Semiconductor / ON Semiconductor IC RESET GENERATOR ULLGA-6</p> |  <p>CAT859TTBI-GT3 AMI Semiconductor / ON Semiconductor IC SUPERVISOR MPU PP 3.08V SOT23</p> |  <p>CAT863STBGI-T3-D3 CAT CAT863STBGI-T3-D3 CAT</p> |
|  <p>CAT863STBI-GT3 AMI Semiconductor / ON Semiconductor IC SUPERVISOR MPU OD 2.93V SOT23</p> |  <p>CAT863MTBI-GT3 AMI Semiconductor / ON Semiconductor IC SUPERVISOR MPU OD 4.38V SOT23</p> |  <p>CAT859STBI-GT3 AMI Semiconductor / ON Semiconductor IC SUPERVISOR MPU PP 2.93V SOT23</p> |  <p>CAT869MTBI-GT3 AMI Semiconductor / ON Semiconductor IC SUPERVISOR MPU PP 4.38V SOT23</p> |

Hot Parts

More

- | | | | | |
|----------------------|---------------------|------------------------|----------------------|------------------------|
| ⊛ 12105E104ZAT2A | ↔ ADP3165JRU-REEL | ⇒ APL5151-37BC-TR | D AQV410EHAX | ⇒ AT93C66B-MAHM-T |
| ⊣ BAV99DW-7 | ⊛ BSM101AR | D BU4816FVE | ⇒ BYV27-600-TAP | ⇒ C1005JB1C154M050BB |
| ⊛ C1608CH1H561K080AA | ⊣ CC0100JRNPO6BN100 | ⊛ CGA3E2X5R1H153M080AA | ↔ DD89N16K-A | ⇒ DSA503-23GE |
| D EM488M1644VTA-7F | ⊛ FDPF5N50FT | ⊣ GCA150AA60 | ⊛ GRM1886R1H360JZ01D | ⇒ HZU6.8GTRF-E |
| ⇒ IDT74FCT163373CTV | ↔ IRFBC40S | ⊛ ISL8489EIB | ⊣ ISL85033IRTZ | ⇒ LCMXO256C-4TN100C-3I |
| ↔ LM5007MMX/NOPB | ⇒ LT1610CS8#TRPBF | D M34281M1-609GP | ⊛ MAX4536ESE | ⊣ MCR03EZHF1502 |
| ⊛ MIC2075-2YM | D MIC2951-03BM | ⇒ MIC59300-1.2YME | ↔ NJU7241F18-TE1 | ⇒ PL611-30-L25SI-R |
| ⊣ PMGD290XN | ⊛ RT1P440C-T112-1 | ↔ SKT100/10E | ⇒ ST1200C14K3L | ⇒ STM8SSPRT |
| ⊛ T90RIA20S90 | ⊣ TC58DVM72A1FT00 | ⊛ TDA9102C/T | D TK11250M | ⇒ TLE2142ACDR |
| ↔ TMK212SD223JG-T | ⊛ TPC8203-H | ⊣ V24C24C100AL | ⊛ VI-J1Z-IY | ⇒ VS-MBRS120TRPBF |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited