







	<b>WCD-9320-0-84WLNSP</b>	
	<b>Manufacturer Part Number:</b>	WCD-9320-0-84WLNSP
<b>Manufacturer/Brand:</b>	QUALCOMM	
<b>Part of Description:</b>	QUALCOMM BGA	
<b>RoHs Status:</b>		
<b>Stock Condition:</b>	New original, 1600 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications	
Part Number	WCD-9320-0-84WLNSP
Manufacturer	QUALCOMM
Description	QUALCOMM BGA
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	1600 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

WCD-9320-0-84WLNSP is New Original in Stock, Search WCD-9320-0-84WLNSP Datasheets, PDF, Inventory at Y-IC.com Online, Order WCD-9320-0-84WLNSP with warrantied and confidence. RFQ WCD-9320-0-84WLNSP : Info@Y-IC.com

You May Be Also Be interested

In:

 <b>WCD-9330-0-119BWLNSP-HR-01-0</b> QUALCOMM QUALCOMM BGA	 <b>WCD-9310-0-71WLNSP-TR-02-0</b> QUALCOMM QUALCOMM BGA	 <b>WCD-9310-0-71WLNSP-TR</b> QUALCOMM QUALCOMM QFN	 <b>WCD-9320-0-84WLNSP-HR-01-0</b> QUALCOMM QUALCOMM QFN
 <b>WCD-9310-0-71WLNSP-SR-02-0</b> QUALCOMM QUALCOMM BGA	 <b>WCD-9330-0-119BWLNSP-TR-01-0</b> QUALCOMM QUALCOMM BGA	 <b>WCD-9310-0-71WLNSP-SR</b> QUALCOMM QUALCOMM QFN	 <b>WCD-9320-0-84WLNSP-TR-01-0</b> QUALCOMM QUALCOMM BGA

Hot Parts

More

- |                        |                         |                       |                       |                        |
|------------------------|-------------------------|-----------------------|-----------------------|------------------------|
| ⚙️ 04023U3R3BAT2A      | ➡️ 0402YD273MAT2A       | ➡️ 1N4762A-TAP        | D 2MBI175P-060        | ➡️ 2MBI200U4B120-50    |
| ⚡ 2MBP600UA120V        | ⚙️ ADA4807-1ARJZ-R7     | D AT25128N-10SI-2.7   | ➡️ B360A-E3/61T       | ➡️ C1608C0G2E151J080AA |
| ⚙️ C2012X7T2W223K125AA | ⚡ CRCW25128K20JNTG-8.2K | ⚙️ DDTA143ZUA-7-F     | ➡️ DLW5ATN500MQ2K     | ➡️ EMQ300-12-16X14     |
| D FDD115H11-56DC24V    | ⚙️ GRM0336R1E6R3DD01D   | ⚡ GRM188R71C394KA88D  | ⚙️ GRM3166R1H151JZ01D | ➡️ HDC-200BP-B         |
| ➡️ HUFA75307D3ST       | ➡️ HVC359TRF            | ⚙️ IRFBA1404P         | ⚡ LM385S8-1.2#PBF     | ➡️ LMV822MMX           |
| ➡️ LT5503EFE           | ➡️ MA4ZD03-TX           | D MBR1545CT           | ⚙️ MIC2954-07YM       | ⚡ NTJD3158CT2G         |
| ⚙️ PCF50600HN          | D PS5701HR              | ➡️ RB168L-40          | ➡️ S-80727AN-DQ-T1    | ➡️ S-817B28AUA-CWR-T2  |
| ⚡ SI4539ADY-T1-GE3     | ⚙️ SI4864DY             | ➡️ SKIIP20NEB06I      | ➡️ SKIIP320TAT08D     | ➡️ SST12LF01-QDF-ZZ123 |
| ⚙️ TC4S66FTE85R        | ⚡ TD56N12KOF            | ⚙️ TLV2217-33KCS      | D ULN2004AIDR         | ➡️ UMK105 CH100FV-F    |
| ➡️ UPA2816T1S          | ⚙️ VI-J6X-EX            | ⚡ VLF252015MT-220M-CA | ⚙️ VS-MURD620CTTRL-M3 | ➡️ XC2S300E-6FGG456C   |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited