









 A Renesas Company	<b>ISL88012IH526Z-T7A</b>
	<b>Manufacturer Part Number:</b> <a href="#">ISL88012IH526Z-T7A</a>
	<b>Manufacturer/Brand:</b> Intersil
	<b>Part of Description:</b> IC VOLTAGE MONITOR DUAL SOT23-5
<b>Datasheets:</b>  <a href="#">ISL88012IH526Z-T7A.pdf</a>	<b>RoHS Status:</b>  Lead free / RoHS
<b>Stock Condition:</b> Compliant New original, Stock Available.	<b>Ship From:</b> Hong Kong
<b>Image may be representation. See specs for product details.</b>	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS

### Specifications

Part Number	<a href="#">ISL88012IH526Z-T7A</a>
Manufacturer	Intersil
Description	IC VOLTAGE MONITOR DUAL SOT23-5
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Open Drain, Push-Pull
Reset	Active High/Active Low
Number of Voltages Monitored	2
Reset Timeout	140 ms Minimum
Voltage - Threshold	2.63V, Adj
Packaging	Tape & Reel (TR)













ISL88012IH526Z-T7A is New Original in Stock, Search ISL88012IH526Z-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88012IH526Z-T7A Intersil with warrantied and confidence. RFQ ISL88012IH526Z-T7A : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<b>In:</b>  <b>ISL88012IH529Z-TK</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5	 <b>ISL88012IH531Z-T7A</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5	 <b>ISL88012IH526Z-TK</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5	 <b>ISL88012IH522Z-T7A</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5
 <b>ISL88012IH529Z-T7A</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5	 <b>ISL88012EVAL1Z</b> Intersil EVALUATION BOARD FOR ISL88012	 <b>ISL88012IH522Z-TK</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5	 <b>ISL88012IH523Z-TK</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5

### Hot Parts

[More](#)

 0402YA4R7KAT2A	 12063D105JAT2A	 AD8323ARU-REEL	 CL10B153KB8WPNC	 CL10B223KA8NNWC
 CSPEMI608G	 DSC2001ROL	 D F0505D-1W	 FB10R06KL4	 FS10864A
 GBLCS05-LF-T74	 GL41Y-E3/96	 GRM0335C1H3R9CD01D	 GRM1885C1H150FA01J	 GRM2196T2A4R5CD01D
 D HIP6521CB	 IRFU9024A	 LA6560-E	 LS7001-3Q16	 LTC3530EDD
 MAX4583CUE+	 MAX628CSA-T	 MAX6956AAX/V	 MAX708SCSA	 MB86A35SPLS-M-EFE1
 MD6203C-C	 MIC4425CWM	 MMSZ5234AS-R1	 P6KE200A	 PBSS304NZ
 PI3V712-AZLEX	 RT9262CS.	 S-80835CNMC-B8UT2G	 S-8220CAA-H6T5S	 S1B-E3/61T
 S5B-M3/57T	 SE5008DMDNC1-R104R	 SI1012CR-T1-GE3	 SI1865DL-T1-E3	 SMA6J20CA
 SN74LVC2G14IDCKRQ1	 THS4226DGQR	 TLC2272IDR	 VD090512H-2W	 VE-201-MX
 VI-27Y-IX	 W25X10CLUXIG	 X15-24S02	 XC6209F28ADR-G	 XC62FP5402TH

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited