

 ANALOG DEVICES AHEAD OF WHAT'S POSSIBLE™	Manufacturer Part Number: ADM6315-26D4ART-RL
	Manufacturer/Brand: ADI (Analog Devices, Inc.)
	Part of Description: IC SUPERVISOR OD 2.63V SOT143
	Datasheets:  ADM6315-26D4ART-RL.pdf
RoHs Status: Contains lead / RoHS non-compliant	Stock Condition: New original, Stock Available.
Ship From: Hong Kong	Shipment Way: DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	

Specifications

Part Number	ADM6315-26D4ART-RL
Manufacturer	ADI (Analog Devices, Inc.)
Description	IC SUPERVISOR OD 2.63V SOT143
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 125°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	TO-253-4, TO-253AA
Supplier Device Package	SOT-143-4
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	1.12 s Minimum
Voltage - Threshold	2.63V
Packaging	Tape & Reel (TR)

ADM6315-26D4ART-RL is New Original in Stock, Search ADM6315-26D4ART-RL Datasheets, PDF, Inventory at Y-IC.com Online, Order ADM6315-26D4ART-RL ADI (Analog Devices, Inc.) with warrantied and confidence. RFQ ADM6315-26D4ART-RL : Info@Y-IC.com







You May Be Also Be interested

In:

 ADM6315-26D4ART-RL7 AD ADM6315-26D4ART-RL7 AD	 ADM6315-26D4ARTZR7 ADI (Analog Devices, Inc.) IC SUPERVISOR OD 2.63V SOT143	 ADM6315-26D3ARTZ-RL7 AD ADM6315-26D3ARTZ-RL7 AD	 ADM6315-26D3ARTZRL ADI (Analog Devices, Inc.) IC SUPERVISOR OD 2.63V SOT143
 ADM6315-26D3ARTRL7 AD ADM6315-26D3ARTRL7 AD	 ADM6315-26D4ARTZ AD ADM6315-26D4ARTZ AD	 ADM6315-26D3ARTZR7 ADI (Analog Devices, Inc.) IC SUPERVISOR OD 2.63V SOT143	 ADM6315-26D4ARTRL7 ADI (Analog Devices, Inc.) IC SUPERVISOR OD 2.63V SOT143

Hot Parts

More

- | | | | | |
|---|--|--|---|---|
|  18122C273KAT2A |  AD7741YRZ |  AD80053KST-36 |  AP1120SLA |  AT83C5121DWT-ICSUL |
|  AWT6624SRM45Q7 |  B82422A3681K100 |  BA5947FM |  BZT55C3V9-GS08 |  C0603C0G1H150K030BA |
|  CSR8615B04-IQQF-R |  CX24153-25MZ |  EL5205IYZ |  EMC1202-AGZQ-TR |  FB2012-10N2R4ET/LF |
|  D FP35R12KT4_B16 |  GRM0336R1HR80BD01D |  GRM1556S1HR60CD01D |  GRM42A7U3F820JW31L |  HFA3524IA |
|  HUF76132S3ST |  IR3812MTRPBF |  IXTX22N100L |  L88M12TL-TL |  LM2940CSX-5.0 |
|  LTST-T670PL |  LTV-703VSTA-PR |  MAX3451EEUD |  MC14574P |  MC908GR60ACFJ |
|  MM3243YRRE |  OPA2188AID |  PAT40012 |  RA201236XX00 |  RSD080N06FRA |
|  RT9603CS |  S-8323H31MC-F4L-T2 |  SA1117H-5.0TR |  SDT49GK16 |  SKKT56/08D |
|  SML4740A |  T221N18EOF |  TDA8290HN/C1 |  TPA3005D2PHP |  TPS2000CDGNR |
|  TPS3838J25DBVRG4 |  VI-250-EV-05 |  VOS617A-2 |  XC9111A301PR-G |  Z86C0812PSC |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited