










	BA5969FP-E2
	Manufacturer Part Number: BA5969FP-E2
	Manufacturer/Brand: LAPIS Semiconductor
	Part of Description: IC BRIDGE DRIVER PAR 28HSOP
Datasheets:  BA5969FP-E2.pdf	RoHs Status:  Lead free / RoHS
Stock Condition: Compliant New original, 1400 pcs Stock Available.	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	BA5969FP-E2
Manufacturer	LAPIS Semiconductor
Description	IC BRIDGE DRIVER PAR 28HSOP
Category	Integrated Circuits (ICs) > PMIC - Full, Half-Bridge
Part Status	1400 pcs Stock
Series	-
Technology	Bipolar
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Features	-
Interface	Logic
Applications	DC Motors, General Purpose
Package / Case	28-SOP (0.295", 7.50mm Width) + 2 Heat Tabs
Supplier Device Package	28-HSOP
Voltage - Supply	4.3 V ~ 9 V
Current - Output / Channel	-
Current - Peak Output	-
Output Configuration	Half Bridge (8)
Fault Protection	Over Temperature
Load Type	Inductive
Rds On (Typ)	-
Voltage - Load	6V
Packaging	Tape & Reel (TR)

BA5969FP-E2 is New Original in Stock, Search BA5969FP-E2 Datasheets, PDF, Inventory at Y-IC.com Online, Order BA5969FP-E2 LAPIS Semiconductor with warrantied and confidence. RFQ BA5969FP-E2 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>Not Actual Photo YIC International Co., Limited.</p> <p>BA5968FP ROHM BA5968FP ROHM</p>	 <p>BA5962FVM-TR LAPIS Semiconductor IC BRIDGE DRIVER PAR 8MSOP</p>	 <p>Not Actual Photo YIC International Co., Limited.</p> <p>BA597 E6327 Infineon BA597 E6327 Infineon</p>	 <p>BA5965FV-E2 LAPIS Semiconductor IC MOTOR DRIVER SSOP</p>
 <p>BA5970FP-E2 LAPIS Semiconductor IC BRIDGE DRIVER PAR 28HSOP</p>	 <p>BA5966FP-E2 LAPIS Semiconductor IC MOTOR DRIVER</p>	 <p>Not Actual Photo YIC International Co., Limited.</p> <p>BA5972AFP-E2 ROHM BA5972AFP-E2 ROHM</p>	 <p>Not Actual Photo YIC International Co., Limited.</p> <p>BA5972FP ROHM BA5972FP ROHM</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|---------------------|-------------------|-------------------|
| ⊛ 06035C102KAJ2A | ↔ 0805YC474JAT2A | ⇒ 24AA32A-I/MS | D AM29F016B-90FI | ⇒ AP83T02GH |
| ⊣ C0603C0G1E330G | ⊛ CB-160808-151 | D CC0603MRX5R6BB226 | ⇒ CL-200Y-C-TS | ⇒ CL21B104KACNUNC |
| ⊛ CMPD914TR | ⊣ DG419BDY-T1-E3 | ⊛ DM74S11N | ↔ ESD7484NCTAG | ⇒ FSTU16862QSP |
| D GRM1555C1H5R1CZ01D | ⊛ GRM2165C1H120JZ01D | ⊣ HZU7.5B3TRF | ⊛ IRF7424TRPBF | ⇒ KET24575HB |
| ⇒ LTC1778EGN#TRPBF | ↔ LTC3129IUD-1#PBF | ⊛ M30290M8T-720HP | ⊣ M38510/14102BEA | ⇒ MAX15119GTM+T |
| ↔ MAX393HAUA+T | ⇒ MAX8675EWN+T | D MC1403DG | ⊛ MDA990-2 | ⊣ MIC2005-0.5YML |
| ⊛ N1314C300 | D N540CH15 | ⇒ PL3500A30P | ↔ PS2561L-1-F3-A | ⇒ PS9701-F4 |
| ⊣ PZM24NB1 | ⊛ R1LV0108ESF-7SR#SO | ↔ RBQ10BM45AFHTL | ⇒ RT9178-31CB. | ⇒ SBR20A100CTB-13 |
| ⊛ SC8863-280CSKTR | ⊣ STF5N52U | ⊛ SVC386T-AL | D SZBZX84C18LT1G | ⇒ T178F04CM |
| ↔ TDF8546TH/N2 | ⊛ TPCA8078 | ⊣ UM3486EESAR | ⊛ WPT170-14 | ⇒ YD25-48S12 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited