


|   |   |
|---|---|
|  | <p><b>BC807-40SN</b></p> <p><b>Manufacturer Part Number:</b> BC807-40SN</p> <p><b>Manufacturer/Brand:</b> ST</p> <p><b>Part of Description:</b> ST SOT23</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 3500 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p> |
|   | <p>Image may be representation.<br/>See specs for product details.</p>  |









**Specifications**

|              |   |
|--------------|---|
| Part Number  | BC807-40SN                                      |
| Manufacturer | ST  |
| Description  | ST SOT23  |
| Category     | Integrated Circuits (ICs) > Specialized Hot ICs |
| Part Status  | 3500 pcs Stock                                  |
| Series       | -   |
| RoHs Status  | Lead free / RoHS Compliant                      |
| Condition    | New Original Stock                              |
| Warranty     | 100% Perfect Functions                          |
| Lead Time    | 2-3days after payment.                          |
| Payment      | PayPal / Telegraphic Transfer / Western Union   |
| Shipping by  | DHL / Fedex / UPS                               |
| Port         | HongKong  |
| RFQ Email    | Info@Y-IC.com                                   |

BC807-40SN is New Original in Stock, Search BC807-40SN Datasheets, PDF, Inventory at Y-IC.com Online, Order BC807-40SN with warrantied and confidence. RFQ BC807-40SN : Info@Y-IC.com

You May Be Also Be interested

In:

|  |  |  |  |
|--|--|--|--|
|  <p><b>BC807-40W E6327</b><br/>INFINEON<br/>BC807-40W E6327 INFINEON</p>  |  <p><b>BC807-40LWF</b><br/>Nexperia<br/>TRANS PNP 45V 0.5A SOT323</p> |  <p><b>BC807-40W,115</b><br/>Nexperia<br/>TRANS PNP 45V 0.5A SOT323</p>            |  <p><b>BC807-40W 250-600</b><br/>CJ<br/>CJ SOT-323 17+</p>          |
|  <p><b>BC807-40QAZ</b><br/>Nexperia<br/>TRANS PNP 45V 0.5A DFN1010D-3</p> |  <p><b>BC807-40LWX</b><br/>Nexperia<br/>TRANS PNP 45V 0.5A SOT323</p> |  <p><b>BC807-40Q-7-F</b><br/>Diodes Incorporated<br/>TRANS NPN 45V 500MA SOT23</p> |  <p><b>BC807-40LZ</b><br/>Nexperia<br/>BC807-40L/SOT23/TO-236AB</p> |

**Hot Parts**

More

- |                        |                          |                        |                      |                    |
|------------------------|--------------------------|------------------------|----------------------|--------------------|
| ⚙️ 08051A430GAT2A      | ➡️ 110Q2G41              | ➡️ 24AA64-I/ST         | D 6MBP20JB060 6MBP20 | ➡️ ADL5531ACPZ-R7  |
| ⚡ AT25DF161-SH-B       | ⚙️ B39941-B9472-P810-S05 | D B3F-3120             | ➡️ BQ27421YZFR-G1D   | ➡️ BSM200GB170DL   |
| ⚙️ C2012X5R1A106M125AB | ⚡ CL10B751KB8NNNC        | ⚙️ CM1000HA-24F        | ➡️ FAN48632UC35X     | ➡️ FJY4009R        |
| D GRM1556R1H270GZ01D   | ⚙️ HCPL-181-06BE         | ⚡ HN1B04FU-Y           | ⚙️ IRKT26/10         | ➡️ IRL530APBF      |
| ➡️ IXFN100N10          | ➡️ LC4032V-5TN-75I       | ⚙️ LT3008EDC-3.3#TRPBF | ⚡ LT3437EDD#TRPBF    | ➡️ LT3971IMSE#PBF  |
| ➡️ LTC2057HVHMS8#PBF   | ➡️ MAX15007AASA+T        | D MAX4167ESA+T         | ⚙️ MAX692CSA         | ⚡ MAX8891EXK18+T   |
| ⚙️ MBR4060PT           | D MEM2012D501RT001       | ➡️ MSB1231-LF          | ➡️ NCP15WF104F03RC   | ➡️ P036RH08CK0     |
| ⚡ P4SMAJ40AG           | ⚙️ PAM2306AYPKB          | ➡️ PIC16C63-04/SP      | ➡️ SDA006-7          | ➡️ SN74LV244ADBR   |
| ⚙️ T481S2000TKM        | ⚡ T491B686K006AT         | ⚙️ TESVC1C106M12R      | D UHE-30726-C        | ➡️ UMK325BJ105MH-T |
| ➡️ UPD16430AGF-3B9     | ⚙️ V300B5C200BL3         | ⚡ VI-26M-MY            | ⚙️ ZMY4V7-GS08       | ➡️ ZTW1R54815      |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited