








	<p>BUK9880-100A</p>
	<p>Manufacturer Part Number: BUK9880-100A</p> <p>Manufacturer/Brand: NXP Semiconductors / Freescale</p> <p>Part of Description: BUK9880-100A NXP</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 13928 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	BUK9880-100A
Manufacturer	NXP Semiconductors / Freescale
Description	BUK9880-100A NXP
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	13928 pcs Stock
Package	SOT-223
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

BUK9880-100A is New Original in Stock, Search BUK9880-100A Datasheets, PDF, Inventory at Y-IC.com Online, Order BUK9880-100A NXP Semiconductors / Freescale with warrantied and confidence. RFQ BUK9880-100A : Info@Y-IC.com

You May Be Also Be interested In:

 <p>BUK9875-60A NXP BUK9875-60A NXP</p>	 <p>BUK9875-100A,115 NXP Semiconductors / Freescale MOSFET N-CH 100V 7A SOT-223</p>	 <p>BUK9880-55 N BUK9880-55 N</p>	 <p>BUK9880-55,135 NXP Semiconductors / Freescale MOSFET N-CH 55V 7.5A SOT223</p>
 <p>BUK9880-55/CU NXP NXP NA</p>	 <p>BUK9875-100A/CU NXP NXP NA</p>	 <p>BUK9875-100A NXP BUK9875-100A NXP</p>	 <p>BUK9880-55,135 Nexperia MOSFET N-CH 55V 7.5A SOT223</p>

Hot Parts

More

- | | | | | |
|----------------|-----------------|-----------------|-----------------|-------------------|
| ⊛ BUK9623-75A | ➔ BUK9624-55A | ➔ BUK9628-100A | D BUK9628-55A | ➔ BUK9629-100B |
| ⊠ BUK962R8-30B | ⊛ BUK9635-100A | D BUK9635-55 | ➔ BUK9635-55A | ➔ BUK9640-100A |
| ⊛ BUK964R4-40B | ⊠ BUK9660-100A | ⊛ BUK9675-100A | ➔ BUK9675-55A | ➔ BUK98150-55 |
| D BUK98150-55A | ⊛ BUK98180-100A | ⊠ BUK98180-55A | ⊛ BUK9830-30 | ➔ BUK9832-55 |
| ➔ BUK9832-55A | ➔ BUK9840-55 | ⊛ BUK9840-55A | ⊠ BUK9875-100A | ➔ BUK9875-60A |
| ➔ BUK9880-55 | ➔ BUK9880-55A | D BUK9907-40ATC | ⊛ BUK9907-55ATE | ⊠ BUK9E04-30B |
| ⊛ BUK9E04-40A | D BUK9E06-55A | ➔ BUK9E08-55B | ➔ BUK9E4R4-40B | ➔ BUK9K29-100E/C4 |
| ⊠ BUK9Y07-30B | ⊛ BUK9Y09-40B | ➔ BUK9Y104-100B | ➔ BUK9Y11-30B | ➔ BUK9Y14-40B |
| ⊛ BUK9Y19-75B | ⊠ BUK9Y22-30B | ⊛ BUK9Y25-60E | D BUK9Y25-80E | ➔ BUK9Y27-40B |
| ➔ BUK9Y29-40E | ⊛ BUK9Y30-75B | ⊠ BUK9Y38-100E | ⊛ BUK9Y3R0-40E | ➔ BUK9Y40-55B |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited