

	<p><b>BGU8007</b></p>
	<p><b>Manufacturer Part Number:</b> BGU8007</p> <p><b>Manufacturer/Brand:</b> NXP</p> <p><b>Part of Description:</b> BGU8007 NXP</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 9958 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	







**Specifications**

Part Number	BGU8007
Manufacturer	NXP
Description	BGU8007 NXP
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	9958 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

BGU8007 is New Original in Stock, Search BGU8007 Datasheets, PDF, Inventory at Y-IC.com Online, Order BGU8007 with warrantied and confidence. RFQ BGU8007 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p><b>BGU8004Z</b> NXP Semiconductors / Freescale IC MMIC AMP LNA WLCSP6</p>	 <p><b>BGU8006</b> NXP BGU8006 NXP</p>	 <p><b>BGU8006Z</b> NXP Semiconductors / Freescale IC AMP GALI 1.559-1.61GHZ 6WLCSP</p>	 <p><b>BGU8004X</b> NXP Semiconductors / Freescale IC MMIC AMP LNA WLCSP6</p>
 <p><b>BGU8007,115</b> NXP Semiconductors / Freescale IC AMP LNA GPS GLONASS SOT886</p>	 <p><b>BGU8006,115</b> NXP Semiconductors / Freescale IC AMP RF LNA FOR GNSS 6WLCSP</p>	 <p><b>BGU8010</b> NXP Semiconductors / Freescale BGU8010 NXP</p>	 <p><b>BGU8009,115</b> NXP Semiconductors / Freescale IC AMP MMIC LNA 6XSON</p>

Hot Parts

More

- |                        |                        |                   |                         |                       |
|------------------------|------------------------|-------------------|-------------------------|-----------------------|
| ⊕ 04023A220CAT2A       | ↔ 06035A131GAT2A       | ⇒ 12065A820GAT2A  | D 18085A332JAT2A        | ↔ AT24C04B-10SU-2.7   |
| ↳ BD9972FV-GE2         | ⊕ BLM15BB121SN1D       | D BXB100-48S05FLT | ⇒ C0603X5R1E471K030BA   | ↔ C2012C0G2A152J060AA |
| ⊕ CEU4J2X7R2A472K125AE | ↳ DAN222MT2L           | ⊕ FGB5N60UNDF     | ↔ FQD2N80TM             | ↔ FT8010MPX           |
| D GAL22V10B-10LPN      | ⊕ GRM1556R1H9R2DZ01D   | ↳ HAT3010R        | ⊕ IPB147N03L            | ↔ IS61LV3216-12K      |
| ⇒ IXGX120N60C3         | ↔ LM2904WHD            | ⊕ LNK6773V        | ↳ MB90347ASPMC-GS-318E1 | ↔ MID400SV            |
| ↔ MSC1191MS-KR1        | ⇒ MT46H16M32LFCX-5IT:B | D NCP1203P100     | ⊕ NL453232T-680J        | ↳ NP75N04VUK-E1-AY    |
| ⊕ P6SMB39A-E3/52       | D PE42692DIBDA-Z       | ⇒ PQ033ES3MXP     | ↔ PS421TQFP100G-A1      | ↔ QM30TF-HE           |
| ↳ QMK212B7332KDHT      | ⊕ R2475ZC28R           | ↔ RJK0852DPB      | ⇒ S1D17901T00500A       | ↔ SC900815G5          |
| ⊕ SPX2810M3-3.3        | ↳ SS22S-E3/61T         | ⊕ ST180S20P2      | D TDA5235HT             | ↔ TK11190CSG          |
| ↔ UMK107BJ104KAHT      | ⊕ UPA672T-T2-A         | ↳ V48B28M250BL    | ⊕ VE-260-28             | ↔ XC6223H171GR-G      |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited