	<p>X40426V14I-2.7</p>
	<p>Manufacturer Part Number: X40426V14I-2.7</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC SUPERVISR CPU IIC LVS 14TSSOP</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X40426V14I-2.7
Manufacturer	Intersil
Description	IC SUPERVISR CPU IIC LVS 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	-
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	-
Reset	-
Reset Timeout	-
Voltage - Threshold	-
Packaging	-

X40426V14I-2.7 is New Original in Stock, Search X40426V14I-2.7 Datasheets, PDF, Inventory at Y-IC.com Online, Order X40426V14I-2.7 Intersil with warrantied and confidence. RFQ X40426V14I-2.7 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X40426V14I-4.5A Intersil IC SUPERVISR CPU IIC LVS 14TSSOP</p>	 <p>X40421V14I-BT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40426V14I Intersil IC SUPERVISR CPU IIC LVS 14TSSOP</p>	 <p>X40426V14I-4.5AT1 Intersil IC SUPERVISR CPU IIC LVS 14TSSOP</p>
 <p>X40421V14I-B Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40426V14I-2.7A Intersil IC SUPERVISR CPU IIC LVS 14TSSOP</p>	 <p>X40421V14I-CT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40426V14I-2.7AT1 Intersil IC SUPERVISR CPU IIC LVS 14TSSOP</p>

Hot Parts

More

- | | | | | |
|---------------------|----------------------|----------------------|-------------------|---------------------|
| ⊛ 08051A470JAT2A | ↔ 1775805-2 | ⇒ 7MBR15UG120 | D ALT6713RM45Q7 | ⇒ AN22142AAVT |
| ⊣ AP1722A-30GC | ⊛ AT17LV256-10PU | D BKO-CA1618-H13 | ⇒ BYM300GB170DN2 | ⇒ BZT52C8V2 |
| ⊛ CC1206ZRY5V8BB105 | ⊣ CS0805KRX7R9BB104 | ⊛ ED771613 | ↔ FDMS86500L | ⇒ FZ2400R17KF6CB2 |
| D G2992BP11U | ⊛ GCM1885C2A152JA16J | ⊣ GJM0335C1E100JB01D | ⊛ HCPL-0466 | ⇒ HUFA75329S3S |
| ⇒ IR3311STRLPBF | ↔ LM20145QMHE/NOBP | ⊛ LTC490CN8#PBF | ⊣ MAX291EPA | ⇒ MAX8645XETI+TG104 |
| ↔ MC3359DWR2 | ⇒ MCM69P618CTQ6 | D MMBT3904HF | ⊛ MT9T001P12STC | ⊣ PKJ4119BPIT |
| ⊛ PSB21521EV1.4-G | D RT8283ALGSP | ⇒ RT9711BPB | ↔ S1117-18PIC | ⇒ SC900738EK |
| ⊣ SGU20N40L | ⊛ SH68F83ZU-00000 | ↔ SI3460DDV-T1-GE3 | ⇒ SN74AHC08PWGR4 | ⇒ SN74LVTH374DBR |
| ⊛ SP6201EM5-L-5-0 | ⊣ STPS400H100TV | ⊛ T588N06TOC | D TA78DS06F | ⇒ TB3100M-13-F |
| ↔ TDA18220HN/C1 | ⊛ TK11235BMCL | ⊣ TNY378GN-TL | ⊛ UMK105CG030CVHF | ⇒ VE-JN0-MY |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited