


	<h2>S-80929CLPF-G6ZTFG</h2>
	<p>Manufacturer Part Number: S-80929CLPF-G6ZTFG</p> <p>Manufacturer/Brand: SII Semiconductor Corporation</p> <p>Part of Description: IC VOLT DETECTOR 2.9V SNT-4A</p> <p>Datasheets:  S-80929CLPF-G6ZTFG.pdf</p> <p>RoHS Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	S-80929CLPF-G6ZTFG
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 2.9V SNT-4A
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-809xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	4-SMD, Flat Leads
Supplier Device Package	SNT-4A
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	18 ms Minimum
Voltage - Threshold	2.9V
Packaging	Tape & Reel (TR)

S-80929CLPF-G6ZTFG is New Original in Stock, Search S-80929CLPF-G6ZTFG Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80929CLPF-G6ZTFG SII Semiconductor Corporation with warrantied and confidence. RFQ S-80929CLPF-G6ZTFG : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80929CNMC SEIKO SEIKO SOT-153SOT23-5</p>	 <p>S-80929CLMC-G6ZT2U SII Semiconductor Corporation IC VOLT DETECTOR 2.9V SOT23-5</p>	 <p>S-80929CNMC-G8ZT SEIKO SEIKO SOT153</p>	 <p>S-80929CLNB-G6ZT2U SII Semiconductor Corporation IC VOLT DETECTOR 2.9V SC-82AB</p>
 <p>S-80929CNMC-G8Z-T2 SEIKO S-80929CNMC-G8Z-T2 SEIKO</p>	 <p>S-80929CNMC-G8Z-G SEIKO SEIKO SOT25</p>	 <p>S-80929CLMC-G6Z-T2 SEIKO SEIKO SOT23-5</p>	 <p>S-80929CLPF-G6ZTFU SII Semiconductor Corporation IC VOLT DETECTOR 2.9V SNT-4A</p>

Hot Parts

More

- | | | | | |
|-----------------|--------------------|---------------|--------------------|-------------------|
| 04023U6R8DAT2A | 113MT120KB | 1DI100D-050 | AC201A1IMLG | ACPL-247-500E |
| BF821/DG/B2 | BU4918FVE | BZG05C24TR3 | BZX84C6V8 | CL31C010CBCNINC |
| CM32180A3OP-AD | DG307AAK | DRV134UA | FJD5553TM | HFA2017-90STR |
| ICS951417AFLFT | IDT5V9885B-008PFGI | IPD05N03LAG | IRF4104PBF. | IRF6607TR |
| IRFB3415 | KA258ADTF | L012050S05 | LD025C222KAB2A | LD053A102GAB2A |
| LK100556NJ-T | LM2576HVT-ADJ/NOPB | LM3203TL | LMH6732MAX | LPC11C14FBD48/301 |
| M30620MCP-222FP | MAX970ESD+T | MCC26-16i03 B | MM74HC132MTCX | MT9V111I29STC |
| N283CH12C | P6SMB200AT3G | SDQ12-100-R | SMA6F15A-M3/6A | SN75ALS172ADWR |
| SP211ET-L | SPB80N06S2-H5 | STP4NK50ZD | T520B227M2R5ATE035 | TBU-CA050-300-WH |
| UMK212B7473KG-T | V300A48H600AL | V375C48C150AL | VI-J01-MZ | YDS-1R505 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited