









	<h2 style="color: #E67E22;">ZL40226LDF1</h2>	
	Manufacturer Part Number:	ZL40226LDF1
	Manufacturer/Brand:	Microsemi
	Part of Description:	IC CLK BUFF MUX 2:8 750MHZ 32QFN
	Datasheets:	1.ZL40226LDF1.pdf 2.ZL40226LDF1.pdf 3.ZL40226LDF1.pdf
Image may be representation. See specs for product details.	RoHS Status:	 Lead free / RoHS
	Stock Condition:	Compliant New original, Stock Available.
	Ship From:	Hong Kong
Shipment Way:		DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	ZL40226LDF1
Manufacturer	Microsemi
Description	IC CLK BUFF MUX 2:8 750MHZ 32QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution), Multiplexer
Frequency - Max	750MHz
Package / Case	32-VFQFN Exposed Pad
Supplier Device Package	32-QFN (5x5)
Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.465 V
Output	LVDS
Input	CML, HCSL, LVCMOS, LVDS, LVPECL
Ratio - Input:Output	2:8
Differential - Input:Output	Yes/Yes
Packaging	Tape & Reel (TR)

ZL40226LDF1 is New Original in Stock, Search ZL40226LDF1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40226LDF1 Microsemi with warrantied and confidence. RFQ
ZL40226LDF1 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ZL40224LDG1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>	 <p>ZL40226LDG1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>	 <p>ZL40224LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>	 <p>ZL40227LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>
 <p>ZL40230LDG1 Microsemi LOW SKEW, LOW ADDITIVE JITTER 3</p>	 <p>ZL40225LDG1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>	 <p>ZL40230LDF1 Microsemi LOW SKEW, LOW ADDITIVE JITTER 3</p>	 <p>ZL40225LDF1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>

Hot Parts

More

- | | | | | |
|-------------------|---------------------|----------------------|---------------------|----------------------|
| ⊕ 04025C472JAT2A | ↔ 06035A391FAT2A | ⇒ 3EB19069-02B | D A3PN060-VQG100I | ↔ ADUM1201CRZ-RL7 |
| ⊖ AF216M245001-T | ⊕ AJ60A-024L-120F08 | D B39841B9011E710A03 | ⇒ BCM56150A0KFSBG | ↔ BYV133F-45 |
| ⊕ CD74HC4052M96 | ⊖ CD74HC4538NSR | ⊕ CDDFN2-T12C | ↔ CSTCE8M00G55A-R0 | ↔ CVM180BB80 |
| D DS1107SM29 | ⊕ DTA013ZUBTL | ⊖ DTC343TKAT146 | ⊕ GDT1668C0 | ↔ GRM1555C1E4R2CZ01D |
| ⇒ HAF1009-91STL-E | ↔ HEDR-8000-2K4 | ⊕ ICL3237CAZ-T | ⊖ IS25LP128-JLLE-TR | ↔ LM20136MH |
| ↔ MAX708EPA+ | ⇒ MURP20040CTG | D NCP1523BFCT2G | ⊕ PE-68841T | ⊖ PP3-12-5 |
| ⊕ REG104GA-A | D SAF1761BE/V1 | ⇒ SBT203-11 | ↔ SI2312DS-T1-E3 | ↔ SIC417CD-T1-E3 |
| ⊖ SM5022A3AH-G-EL | ⊕ SSC-TWH104-HL | ↔ SSM5H05TU | ⇒ ST7FOXK1T6 | ↔ STM8AF6146TC |
| ⊕ SUD50N04-13P | ⊖ SUP75P05 | ⊕ TB2901HQ | D TLZ24C-GS08 | ↔ TS3USB31RSER |
| ↔ UCC27511AQBVRQ1 | ⊕ UCC3626PWTRG4 | ⊖ VI-810035 | ⊕ VNI401OK | ↔ XC61FC1852MRN |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited