


	<b>Manufacturer Part Number:</b> EP7309-CVZ
	<b>Manufacturer/Brand:</b> Cirrus Logic
	<b>Part of Description:</b> IC MPU EP7 74MHZ 208LQFP
	<b>Datasheets:</b>  EP7309-CVZ.pdf
	<b>RoHS Status:</b>  Lead free / RoHS
	<b>Stock Condition:</b> Compliant New original, 1400 pcs Stock Available.
	<b>Ship From:</b> Hong Kong
Image may be representation. See specs for product details.	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS









### Specifications

Part Number	EP7309-CVZ
Manufacturer	Cirrus Logic
Description	IC MPU EP7 74MHZ 208LQFP
Category	Integrated Circuits (ICs) > Embedded - Microprocessors
Part Status	1400 pcs Stock
Series	EP7
Operating Temperature	0°C ~ 70°C (TA)
Package / Case	208-LQFP
Supplier Device Package	208-LQFP
Core Processor	ARM7TDMI
Speed	74MHz
Ethernet	-
USB	-
Voltage - I/O	2.5V, 2.7V, 3.0V, 3.3V
Number of Cores/Bus Width	1 Core, 32-Bit
Co-Processors/DSP	-
RAM Controllers	-
Graphics Acceleration	No
Display & Interface Controllers	Keypad, LCD, Touchscreen
SATA	-
Security Features	Hardware ID
Additional Interfaces	DAI, IrDA, SSI, UART
Packaging	Tray

EP7309-CVZ is New Original in Stock, Search EP7309-CVZ Datasheets, PDF, Inventory at Y-IC.com Online, Order EP7309-CVZ Cirrus Logic with warrantied and confidence. RFQ EP7309-CVZ : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>EP7311-CB</b> Cirrus Logic IC MPU EP7 74MHZ 256BGA</p>	 <p><b>EP7311-CV-90</b> Cirrus Logic IC MPU EP7 90MHZ 208LQFP</p>	 <p><b>EP7309-CBZ</b> Cirrus Logic IC MPU EP7 74MHZ 256BGA</p>	 <p><b>EP7311-CB-90</b> Cirrus Logic IC MPU EP7 90MHZ 256BGA</p>
 <p><b>EP7309-CB</b> Cirrus Logic IC MPU EP7 74MHZ 256BGA</p>	 <p><b>EP7311-IB</b> Cirrus Logic IC MPU EP7 74MHZ 256BGA</p>	 <p><b>EP7311-CV</b> Cirrus Logic IC MPU EP7 74MHZ 208LQFP</p>	 <p><b>EP7256BQC208</b> ALTERA ALTERA QFP</p>

### Hot Parts

More

- |                      |                        |                  |                   |                      |
|----------------------|------------------------|------------------|-------------------|----------------------|
| ⊕ 0402YA110JAT2A     | ↔ 06031A101GAT2A       | ⇒ 1206GC561KAT2A | D 2KB433/802      | ⇒ AD5303ARUZ         |
| ⊖ AM29F400B-150EC    | ⊕ BD12KA5FP-E2         | D BD8654FS-HVE2  | ⇒ BZT52C13LP-7    | ⇒ CL10B473JB8NNNC    |
| ⊕ CL21C180GBANNNC    | ⊖ CS410899B            | ⊕ DSP1600A35     | ↔ FSA646UCX       | ⇒ GJM1555C1H3R0CB01J |
| D GRM0335C1ER70BZ01D | ⊕ GRM155R60J334ME01J   | ⊖ ISL9N327AD3ST  | ⊕ KTS6029-2       | ⇒ L08053R9DEWTR      |
| ⇒ LM2579R-ADJ        | ↔ LM317MDTRKG          | ⊕ LT1782IS5      | ⊖ LT6004IDD#TRPBF | ⇒ MAX5186BEEI+       |
| ↔ MAX6355LSUT-T      | ⇒ MAZS051008SO         | D MC100EL05DR2   | ⊕ MC3479PG        | ⊖ MC78L05F-TP        |
| ⊕ MCP100T-300I/TT    | D MD51V65165E-50TAZ03B | ⇒ MDS1521URH     | ↔ NDS9952_NL      | ⇒ NXA66-12P3V3C      |
| ⊖ OB2225MCPA         | ⊕ P083A2007            | ↔ P279-F11-53    | ⇒ PC3SH21YFZBF    | ⇒ PCA9527DP          |
| ⊕ PTVS5V0S1UR        | ⊖ R0717LS14G           | ⊕ RB083L-20TE25  | D SD600R22S50P    | ⇒ SM3317NSQA         |
| ↔ SN54LS21J          | ⊕ TAS5105L             | ⊖ TDA8579T/N1    | ⊕ VI-24Y-EY       | ⇒ VNS1NV04DPTR-E     |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited