

	<p>MIC1832N</p>
	<p>Manufacturer Part Number: MIC1832N</p> <hr/> <p>Manufacturer/Brand: Micrel / Microchip Technology</p> <hr/> <p>Part of Description: IC SUPERVISOR 2.88/2.55V 8-DIP</p> <hr/> <p>Datasheets:  MIC1832N.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	MIC1832N
Manufacturer	Micrel / Microchip Technology
Description	IC SUPERVISOR 2.88/2.55V 8-DIP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	8-DIP (0.300", 7.62mm)
Supplier Device Package	8-PDIP
Output	Open Drain or Open Collector
Reset	Active High/Active Low
Number of Voltages Monitored	1
Reset Timeout	250 ms Minimum
Voltage - Threshold	2.55V, 2.88V
Packaging	Tube

MIC1832N is New Original in Stock, Search MIC1832N Datasheets, PDF, Inventory at Y-IC.com Online, Order MIC1832N Micrel / Microchip Technology with warrantied and confidence. RFQ MIC1832N : Info@Y-IC.com



You May Be Also Be interested

In:

 <p>MIC1832MY Micrel / Microchip Technology IC SUPERVISOR 2.88/2.55V 8-SOIC</p>	 <p>MIC1832NY Micrel / Microchip Technology IC SUPERVISOR 2.88/2.55V 8-DIP</p>	 <p>MIC184BMM Micrel / Microchip Technology SENSOR TEMP I2C/SMBUS 8MSOP</p>	 <p>mic1832mtr MIC MIC MIC</p>
 <p>MIC1832MYTR MIC MIC1832MYTR MIC</p>	 <p>MIC184BM Micrel / Microchip Technology SENSOR TEMP I2C/SMBUS 8SOIC</p>	 <p>MIC1832YM MIC MIC1832YM MIC</p>	 <p>MIC184BM-TR Micrel / Microchip Technology SENSOR TEMP I2C/SMBUS 8SOIC</p>

Hot Parts

[More](#)

- | | | | | |
|--|---|--|---|---|
|  06033C473MAT2A |  06035C103K4Z2A |  12105A152JAT2A |  D 160MT060KB |  1808WA101MAJ3A |
|  2225HC102MAT1A\SB |  ADR443BRZ-REEL7 |  D AK4643EN-L |  ➔ ATMEGA649-16MU |  ➔ BCX68-25 |
|  C0603JB1C472M030BA |  ➔ CB2012T100M |  ➔ CGA4J3X8R1C684K125AB |  ➔ CGA9N3X7R2E105K230KE |  ➔ CL05B561KA5NNNC |
|  D DCR1596SW51 |  ➔ DG2714DL-T1-E3 |  ➔ DMG4800LFG-7 |  ➔ DT425N16KOF |  ➔ ECQ-E6564KF |
|  ➔ FD1200R17KE3 |  ➔ FDG6303N-NL |  ➔ FQU4N20TU |  ➔ GRM2196P2A7R6DZ01D |  ➔ INA188IDR |
|  ➔ IPD04N03LB |  ➔ ISL6609AIRZ |  D LB1933M-MPB-E |  ➔ LP3875ESX-ADJ |  ➔ LT3689EMSE#PBF |
|  ➔ MC74VHCT573ADTRG |  D MIC5237-3.3BU |  ➔ NLC322522T-330K |  ➔ P5NK80ZFP |  ➔ PM8305-LGI |
|  ➔ RBE05AS20AT2R |  ➔ S71PL254JD0BFWTBO |  ➔ SC1453ITSK2.8TRT |  ➔ SCAN92LV090SLCX |  ➔ SG800EX22 |
|  ➔ SI9431DY-T1-E3 |  ➔ T378N26TOF |  ➔ TG110-S050P2TR |  D TS271ACN |  ➔ TSV6391ILT |
|  ➔ TT142N16KOF |  ➔ US1G/11T |  ➔ V24C28T100AL |  ➔ VI-J6V-IW |  ➔ VIQ30-06D014 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited