
	<p><b>X93155UM8IZ</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">X93155UM8IZ</a></p> <p><b>Manufacturer/Brand:</b> Intersil</p> <p><b>Part of Description:</b> IC XDCP 32-TAP 50K 3-WIRE 8-MSOP</p> <p><b>Datasheets:</b>  <a href="#">X93155UM8IZ.pdf</a></p> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X93155UM8IZ
Manufacturer	Intersil
Description	IC XDCP 32-TAP 50K 3-WIRE 8-MSOP
Category	Integrated Circuits (ICs) > Data Acquisition - Digital
Part Status	Require For Quote & Check Stock
Series	XDCP™
Operating Temperature	-40°C ~ 85°C
Features	-
Interface	Up/Down (U/D, INC, CS)
Configuration	Rheostat
Tolerance	±25%
Package / Case	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Supplier Device Package	8-MSOP
Number of Circuits	1
Voltage - Supply	5V
Memory Type	Non-Volatile
Resistance (Ohms)	50k
Taper	Linear
Number of Taps	32
Temperature Coefficient (Typ)	±35 ppm/°C
Resistance - Wiper (Ohms) (Typ)	-
Packaging	Tube

X93155UM8IZ is New Original in Stock, Search X93155UM8IZ Datasheets, PDF, Inventory at Y-IC.com Online, Order X93155UM8IZ Intersil with warrantied and confidence. RFQ  
X93155UM8IZ : [Info@Y-IC.com](mailto:Info@Y-IC.com)

You May Be Also Be interested

In:

 <p><b>X93155UM8IZT1</b> Intersil IC POT DGTL 50K OHM 8-MSOP</p>	 <p><b>X93154UPD</b> XICOR X93154UPD XICOR</p>	 <p><b>X93154UU8IZ-3T1</b> Intersil IC POT DGTL LP LN 50K OHM 8-TDFN</p>	 <p><b>X93156UM8IZ-2.7T1</b> Intersil IC POT DGTL 50K OHM 8-MSOP</p>
 <p><b>X93156UM8I-2.7</b> Intersil IC XDCP 32-TAP 50K 3-WIRE 8-MSOP</p>	 <p><b>X93155UM8IT1</b> Intersil IC XDCP 32-TAP 50K 3-WIRE 8-MSOP</p>	 <p><b>X93156UM8I-2.7T1</b> Intersil IC XDCP 32-TAP 50K 3-WIRE 8-MSOP</p>	 <p><b>X93155UM8I</b> Intersil IC DIGITAL POT 50K 32TAP 8-MSOP</p>

Hot Parts

More

- |                      |                     |                      |                   |                       |
|----------------------|---------------------|----------------------|-------------------|-----------------------|
| ⊕ 04025A150GAT2A     | ↔ ACT6907UCADJ      | ⇒ ADM202JRNZ         | D ADP125ACPZ-RL   | ⇒ AOWF12N50           |
| ⊖ APL5308-18DC-TR    | ⊕ APTCC3055         | D AT25DF321-SU       | ⇒ AT29C010A-90TC  | ⇒ ATZB-A24-U0R        |
| ⊕ BC847BT/BE         | ⊖ BR1102W-640-TR    | ⊕ B5TL4560K          | ↔ BUK7623-75A     | ⇒ C0402X7R1A471K020BC |
| D CD40105BD          | ⊕ CPH5802-TL        | ⊖ FGPF50N33BT        | ⊕ GAL18V10B-15LJN | ⇒ GCM1555C1H5R3DA16D  |
| ⇒ GRM033C80J823ME15D | ↔ LM-U64-06         | ⊕ LM3543M-LL         | ⊖ LM4040AIM3X-5.0 | ⇒ LMX2433TMCX         |
| ↔ LSP3602TCADJAK     | ⇒ LT1004ID-2.5      | D LTC3836EUFDF#TRPBF | ⊕ MAX1844EEP+TGC1 | ⊖ MAX708RCSA          |
| ⊕ MC145151DW2R2      | D MCP1826S-5002E/AB | ⇒ MT49H16M36FM-33:A  | ↔ N283SH16        | ⇒ NLAS5223BMUR2G      |
| ⊖ PZU5.1B1           | ⊕ S-1172B12-E6      | ↔ S1A2402C01-D0B0    | ⇒ S9S08SL8F1MTJR  | ⇒ SF200AA10           |
| ⊕ SFHG89GA002        | ⊖ SG1200GXH25       | ⊕ SKKD81/12E         | D STP20NK50Z      | ⇒ SW08CXC30C          |
| ↔ V48A12C500A3       | ⊕ VE-J12-CX         | ⊖ VI-231-CW/F2       | ⊕ VT2080C-E3/4W   | ⇒ YFF18PH0J105MT009N  |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited